

Appendix A **Marked Up Version of Abstract**

A screw element with a tool engagement means-(5, 6) and a spring element (8)-which is formed on the screw element in one piece in coaxial relationship with the screw axis (7)-and which with its free edge defines a workpiece contact plane which is perpendicular to the screw axis and which is at an axial spacing from the screw element-(1), is distinguished in that the spring element-(8) is mounted at the periphery of the screw element, that is to say a screw head-(4) or a screw nut, it projects radially beyond the periphery and it forms a workpiece contact means-(9) which is disposed outside the periphery and which is in concentric relationship with the screw axis-(7).

(Figure 1)